



GEP

RECEIVED
US EPA, DALLAS, TX
ASSOCIATE DIRECTOR

18 NOV - 1 AM 10:35

2001 E 70th Street
Suite 503
Shreveport, LA 71105
PHONE (318) 797-8636
FAX (318) 798-0478
www.c-ka.com

October 25, 2018

COMPLIANCE ASSURANCE
& ENFORCEMENT DIV.

BATON ROUGE, LA
PHONE (225) 755-1000
FAX (225) 751-2010

HOUSTON, TX
PHONE (281) 397-9016
FAX (281) 397-6637

LAKE CHARLES, LA
PHONE (337) 625-6577
FAX (337) 625-6580

Director – Air, Pesticides, and Toxic Division
U.S. Environmental Protection Agency Region VI
1445 Ross Ave., Suite 1200
Dallas, TX 75202

Re: GEP Haynesville, LLC
1425 Lake Front Circle
The Woodlands, TX 77380
OOOOa Annual Report

Dear Sir/Madam:

GEP Haynesville, LLC (GEPH) respectfully submits the enclosed annual NSPS Subpart OOOOa report for the compliance period of August 2, 2017 to August 2, 2018 with a due date of October 31, 2018. A copy of the OOOOa report has also been sent to the Louisiana Department of Environmental Quality.

As required by 40 CFR 60.5420a(b)(1)(iv), based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

If you or your staff have any questions or require additional information, please contact me at (318) 797-8636 or Michael Gary (GEPH) at (318) 214-4936.

Sincerely,
CK Associates

Gordon R. Moore, P.E.
Area Manager/ Sr. Engineer

Enclosures as stated.

NSPS OOOa Annual Report

40 CFR 60.5420a(b)

Company Information and Certification

- (1) The general information specified in paragraphs (b)(1)(i) through (iv) of this section for all reports.
- (i) The company name, facility site name associated with the affected facility, US Well ID or US Well ID associated with the affected facility, if applicable, and address of the affected facility. If an address is not available for the site, include a description of the site location and provide the latitude and longitude coordinates of the site in decimal degrees to an accuracy and precision of five (5) decimals of a degree using the North American Datum of 1983.
- (ii) An identification of each affected facility being included in the annual report.
- (iii) Beginning and ending dates of the reporting period.
- (iv) A certification by a certifying official of truth, accuracy, and completeness. This certification shall state that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

Company Name:

GEP Haynesville, LLC

Mailing Address:

1425 Lake Front Circle
The Woodlands, TX 77380

Technical Contact:

Michael D. Gary

Phone:

(318) 214-4936

Email:

mgary@gephaynesville.com

Date Report Submitted:

Certification by Responsible Official

Based on information and belief formed after reasonable inquiry, the statements and information in this document are true accurate and complete.

Name of Certifying Official:

Margaret W. Molleston

Title:

President and Chief Executive Officer


Email:

MMOLLESTON@geosouthernenergy.com

Phone:

281-363-9161

Signature:



Date:

October 29, 2018

Instructions for Spreadsheet Template

Purpose:

This spreadsheet template was designed by the U.S. EPA to facilitate annual reporting for Oil and Gas Facilities under 40 CFR part 60, subpart OOOOa. CEDRI is accessed through the EPA's Central Data Exchange (<https://cdx.epa.gov>).

Electronic reporting:

Electronic submission of annual reports through the EPA's Compliance and Emissions Data Reporting (CEDRI) is required under §60.5420a(b).

The CEDRI spreadsheet template upload feature allows you to submit data in a single report for a single facility or multiple facilities, as well as multiple sites, using this EPA provided Excel workbook. Data for the site(s) must be entered into the worksheet labeled "Site Information" in this Excel workbook. Each row in the "Site Information" worksheet includes the data for a single site. The Site Record No. will be used to match the information on each tab to the appropriate site.

IMPORTANT: For each site/facility record found in the "Site Information" worksheet, you may reference a single file attachment that includes all information for each citation found in the workbook or provide individual file names for each individual citation record. In the examples provided in the workbook, we provide both as an example.

The spreadsheet must be uploaded into CEDRI as a single ZIP file, which must include this Excel workbook and any related attachments that were referenced in any of the worksheets found in the workbook (e.g., the Certification file found in the "Site Information" worksheet).

Note: If you are uploading file attachments for your report, the uploaded files may be in any format (e.g., zip, docx, PDF). If you would like to include an Excel file(s) as an attachment, you must first zip the excel file(s) into a separate ZIP file to the master ZIP file that will be uploaded into CEDRI.

Once all data have been entered in the worksheet, combine this Excel workbook and all attachment files (including any ZIP file containing separate excel file(s), if applicable) into a single ZIP file for upload to CEDRI.

Please ensure your report includes all of the required data elements found in the listed citations below for this spreadsheet upload submission.

You must submit annual reports containing the information specified in paragraphs (b)(1) through (8) and (12) of this section. You must submit annual reports following the procedure specified in paragraph (b)(11) of this section.

§60.5420a What are my notification, reporting, and recordkeeping requirements?

(b) **Reporting requirements.** You must submit annual reports containing the information specified in paragraphs (b)(1) through (8) and (12) of this section and performance test reports as specified in paragraph (b)(9) or (10) of this section, if applicable, except as provided in paragraph (b)(13) of this section. You must submit annual reports following the procedure specified in paragraph (b)(11) of this section. The initial annual report is due no later than 90 days after the end of the initial compliance period as determined according to §60.5410a. Subsequent annual reports are due no later than same date each year as the initial annual report. If you own or operate more than one affected facility, you may submit one report for multiple affected facilities provided the report contains all of the information required as specified in paragraphs (b)(1) through (8) of this section, except as provided in paragraph (b)(13) of this section. Annual reports may coincide with title V reports as long as all the required elements of the annual report are included. You may arrange with the Administrator a common schedule on which reports required by this part may be submitted as long as the schedule does not extend the reporting period.

(1) The general information specified in paragraphs (b)(1)(i) through (iv) of this section for all reports.

(i) The company name, facility site name associated with the affected facility, US Well ID or US Well ID associated with the affected facility, if applicable, and address of the affected facility. If an address is not available for the site, include a description of the site location and provide the latitude and longitude coordinates of the site in decimal degrees to an accuracy and precision of five (5) decimals of a degree using the North American Datum of 1983.

(ii) An identification of each affected facility being included in the annual report.

(iii) Beginning and ending dates of the reporting period.

(iv) A certification by a certifying official of truth, accuracy, and completeness. This certification shall state that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

(2) For each well affected facility, the information in paragraphs (b)(2)(i) through (iii) of this section.

(i) Records of each well completion operation as specified in paragraphs (c)(1)(i) through (iv) and (vi) of this section, if applicable, for each well affected facility conducted during the reporting period. In lieu of submitting the records specified in paragraph (c)(1)(i) through (iv) of this section, the owner or operator may submit a list of the well completions with hydraulic fracturing completed during the reporting period and the records required by paragraph (c)(1)(v) of this section for each well completion.

(ii) Records of deviations specified in paragraph (c)(1)(ii) of this section that occurred during the reporting period.

(iii) Records specified in paragraph (c)(1)(vii) of this section, if applicable, that support a determination under 60.5432a that the well affected facility is a low pressure well as defined in 60.5430a.

(3) For each centrifugal compressor affected facility, the information specified in paragraphs (b)(3)(i) through (iv) of this section.

(i) An identification of each centrifugal compressor using a wet seal system constructed, modified or reconstructed during the reporting period.

(ii) Records of deviations specified in paragraph (c)(2) of this section that occurred during the reporting period.

(iii) If required to comply with §60.5380a(a)(2), the records specified in paragraphs (c)(6) through (11) of this section.

(iv) If complying with §60.5380a(a)(1) with a control device tested under §60.5413a(d) which meets the criteria in §60.5413a(d)(11) and §60.5413a(e), records specified in paragraph (c)(2)(i) through (c)(2)(vii) of this section for each centrifugal compressor using a wet seal system constructed, modified or reconstructed during the reporting period.

(4) For each reciprocating compressor affected facility, the information specified in paragraphs (b)(4)(i) and (ii) of this section.

(i) The cumulative number of hours of operation or the number of months since initial startup or since the previous reciprocating compressor rod packing replacement, whichever is later. Alternatively, a statement that emissions from the rod packing are being routed to a process through a closed vent system under negative pressure.

(ii) Records of deviations specified in paragraph (c)(3)(iii) of this section that occurred during the reporting period.

(5) For each pneumatic controller affected facility, the information specified in paragraphs (b)(5)(i) through (iii) of this section.

(i) An identification of each pneumatic controller constructed, modified or reconstructed during the reporting period, including the identification information specified in §60.5390a(b)(2) or (c)(2).

(ii) If applicable, documentation that the use of pneumatic controller affected facilities with a natural gas bleed rate greater than 6 standard cubic feet per hour are required and the reasons why.

(iii) Records of deviations specified in paragraph (c)(4)(v) of this section that occurred during the reporting period.

(6) For each storage vessel affected facility, the information in paragraphs (b)(6)(i) through (vii) of this section.

(i) An identification, including the location, of each storage vessel affected facility for which construction, modification or reconstruction commenced during the reporting period. The location of the storage vessel shall be in latitude and longitude coordinates in decimal degrees to an accuracy and precision of five (5) decimals of a degree using the North American Datum of 1983.

- (ii) Documentation of the VOC emission rate determination according to §60.5395a(e) for each storage vessel that became an affected facility during the reporting period or is returned to service during the reporting period.
- (iii) Records of deviations specified in paragraph (c)(5)(iii) of this section that occurred during the reporting period.
- (iv) A statement that you have met the requirements specified in §60.5410a(h)(2) and (3).
- (v) You must identify each storage vessel affected facility that is removed from service during the reporting period as specified in §60.5395a(c)(1)(ii), including the date the storage vessel affected facility was removed from service.
- (vi) You must identify each storage vessel affected facility returned to service during the reporting period as specified in §60.5395a(c)(3), including the date the storage vessel affected facility was returned to service.
- (vii) If complying with §60.5395a(a)(2) with a control device tested under §60.5413a(d) which meets the criteria in §60.5413a(d)(11) and §60.5413a(e), records specified in paragraphs (c)(5)(vi)(A) through (F) of this section for each storage vessel constructed, modified, reconstructed or returned to service during the reporting period.

(7) For the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each compressor station within the company-defined area, the records of each monitoring survey including the information specified in paragraphs (b)(7)(i) through (xii) of this section. For the collection of fugitive emissions components at a compressor station, if a monitoring survey is waived under §60.5397a(g)(5), you must include in your annual report the fact that a monitoring survey was waived and the calendar months that make up the quarterly monitoring period for which the monitoring survey was waived.

- (i) Date of the survey.
- (ii) Beginning and end time of the survey.
- (iii) Name of operator(s) performing survey. If the survey is performed by optical gas imaging, you must note the training and experience of the operator.
- (iv) Ambient temperature, sky conditions, and maximum wind speed at the time of the survey.
- (v) Monitoring instrument used.
- (vi) Any deviations from the monitoring plan or a statement that there were no deviations from the monitoring plan.
- (vii) Number and type of components for which fugitive emissions were detected.
- (viii) Number and type of fugitive emissions components that were not repaired as required in §60.5397a(h).
- (ix) Number and type of difficult-to-monitor and unsafe-to-monitor fugitive emission components monitored.
- (x) The date of successful repair of the fugitive emissions component.
- (xi) Number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair.
- (xii) Type of instrument used to resurvey a repaired fugitive emissions component that could not be repaired during the initial fugitive emissions finding.

(8) For each pneumatic pump affected facility, the information specified in paragraphs (b)(8)(i) through (iii) of this section.

- (i) For each pneumatic pump that is constructed, modified or reconstructed during the reporting period, you must provide certification that the pneumatic pump meets one of the conditions described in paragraphs (b)(8)(i)(A), (B) or (C) of this section.
 - (A) No control device or process is available on site.
 - (B) A control device or process is available on site and the owner or operator has determined in accordance with §60.5393a(b)(5) that it is technically infeasible to capture and route the emissions to the control device or process.
 - (C) Emissions from the pneumatic pump are routed to a control device or process. If the control device is designed to achieve less than 95 percent emissions reduction, specify the percent emissions reductions the control device is designed to achieve.
- (ii) For any pneumatic pump affected facility which has been previously reported as required under paragraph (b)(8)(i) of this section and for which a change in the reported condition has occurred during the reporting period, provide the identification of the pneumatic pump affected facility and the date it was previously reported and a certification that the pneumatic pump meets one of the conditions described in paragraphs (b)(8)(i)(A), (B) or (C) or (D) of this section.
 - (A) A control device has been added to the location and the pneumatic pump now reports according to paragraph (b)(8)(i)(C) of this section.
 - (B) A control device has been added to the location and the pneumatic pump affected facility now reports according to paragraph (b)(8)(i)(B) of this section.
 - (C) A control device or process has been removed from the location or otherwise is no longer available and the pneumatic pump affected facility now report according to paragraph (b)(8)(i)(A) of this section.
 - (D) A control device or process has been removed from the location or is otherwise no longer available and the owner or operator has determined in accordance with §60.5393a(b)(5) through an engineering evaluation that it is technically infeasible to capture and route the emissions to another control device or process.
- (iii) Records of deviations specified in paragraph (c)(16)(ii) of this section that occurred during the reporting period.

(12) You must submit the certification signed by the qualified professional engineer according to §60.5411a(d) for each closed vent system routing to a control device or process.

(11) You must submit reports to the EPA via the CEDRI. (CEDRI can be accessed through the EPA's CDX (<https://cdx.epa.gov/>)) You must use the appropriate electronic report in CEDRI for this subpart or an alternate electronic file format consistent with the extensible markup language (XML) schema listed on the CEDRI Web site (<https://www3.epa.gov/ttn/chief/cedri/>). If the reporting form specific to this subpart is not available in CEDRI at the time that the report is due, you must submit the report to the Administrator at the appropriate address listed in §60.4. Once the form has been available in CEDRI for at least 90 calendar days, you must begin submitting all subsequent reports via CEDRI. The reports must be submitted by the deadlines specified in this subpart, regardless of the method in which the reports are submitted.

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report

For each affected facility, an owner or operator must include the information specified in paragraphs (b)(1)(i) through (iv) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

SITE INFORMATION

Facility Record No. *	Company Name * (\$60.5420a(b)(1)(i))	Facility Site Name * (\$60.5420a(b)(1)(i))	US Well ID or US Well ID Associated with the Affected Facility, if applicable. * (\$60.5420a(b)(1)(i))	Address of Affected Facility * (\$60.5420a(b)(1)(i))	Address 2	City * (\$60.5420a(b)(1)(i))	County * (\$60.5420a(b)(1)(i))	State Abbreviation *	Zip Code *	Responsible Agency Facility ID (State Facility Identifier)
1	GEP Haynesville, LLC	Bertolla 30-19HC 1-ALT & 30-31HC 1&2-ALT	17-081-21527-00	-	-	East Point	Red River	LA	71019	G2380
2	GEP Haynesville, LLC	Cecile Land 9-4HC 1&2-ALT	17-081-21530-00 & 17-081-21531-00	-	-	East Point	Red River	LA	71019	G2380
3	GEP Haynesville, LLC	GEP ETAL 9-4HC 1&2-ALT	17-081-21523-00 & 17-081-21524-00	-	-	East Point	Red River	LA	71019	G2380
4	GEP Haynesville, LLC	James Marston 30-19HC 1-ALT & 30H-1	17-081-21532-00	-	-	East Point	Red River	LA	71019	G2380
5	GEP Haynesville, LLC	James Marston 30-19HC 2&3-ALT & 30-31HC 1&2-ALT	17-081-21525-00 & 17-081-21526-00	-	-	East Point	Red River	LA	71019	G2380
6	GEP Haynesville, LLC	Bolan ETAL 26-35HC 1,2 ALT	17-081-21543-00 & 17-081-21544-00	-	-	East Point	Red River	LA	71019	G2380
7	GEP Haynesville, LLC	Bolan ETAL 27-34HC 001 ALT	17-081-21542-00	-	-	East Point	Red River	LA	71019	G2380
8	GEP Haynesville, LLC	Bollingham 18-7HC 001-ALT & 002-ALT	17-081-21548-00 & 17-081-21549-00	-	-	Martin	Red River	LA	71019	G2380
9	GEP Haynesville, LLC	Bundrick 35-2 HC 001-ALT, 002-ALT & Bundrick 35H 001	17-081-21545-00 & 17-081-21546-00	-	-	East Point	Red River	LA	71019	G2380
10	GEP Haynesville, LLC	Olympia Min 2-11HC 001-ALT & Olympia Min 2-35HC 001	17-085-22461-00	-	-	Belmont	Sabine	LA	71406	G2380
11	GEP Haynesville, LLC	BRP LLC 23H-001ALT & Sustainable 23 001	17-031-26482-00	-	-	Mansfield	DeSoto	LA	71052	G2380
12	GEP Haynesville, LLC	Marr ETAL 22-27HC-001 & 002	17-031-26523-00 & 17-031-26524-00	-	-	Mansfield	DeSoto	LA	71052	G2380
13	GEP Haynesville, LLC	Madden 20-17HC 001-ALT, 17H 001 & 20H 001	17-081-21569-00	-	-	Hall Summit	Red River	LA	71034	G2380
14	GEP Haynesville, LLC	Deanna Sistrunk 16H-02, 03, & 04 ALT and 9H 01, 02, & 03 ALT	17-085-22359-00, 17-085-22358-00, & 17-085-22357-00	-	-	Mitchell	Sabine	LA	71419	G2380
15	GEP Haynesville, LLC	Thomas Greer ETAL 16H-1, 17H-1 & Terry Greer 16H-1	17-085-22472-00 & 17-085-22473-00	-	-	Mitchell	Sabine	LA	71419	G2380
16	GEP Haynesville, LLC	Caney Creek Land 6H-2 and Caney Creek Land 6-1	17-081-21572-00	-	-	Coushatta	Red River	LA	71019	G2380
17	GEP Haynesville, LLC	Moham ETAL 25-36HC 1,2,3 ALT	17-031-26558-00, 17-031-26572-00, & 17-031-26573-00	-	-	Kickapoo	DeSoto	LA	71030	G2380
18	GEP Haynesville, LLC	Two Mile 25-36HC 1ALT	17-031-26571-00	-	-	Kickapoo	DeSoto	LA	71030	G2380
19	GEP Haynesville, LLC	KHL Minerals 16-21HC-1	17-015-25114-00	-	-	Sligo	Bossier	LA	71037	G2380
20	GEP Haynesville, LLC	Bozeman ETAL 20H 1,2 ALT	17-031-26581-00 & 17-031-26582-00	-	-	Pleasant Hill	DeSoto	LA	71065	G2380
21	GEP Haynesville, LLC	Hall ETAL 16-21HC 001	17-031-26635-00	-	-	Stonewall	DeSoto	LA	71078	G2380
22	GEP Haynesville, LLC	Joan Brandon ETAL 20H 1,2,3 ALT & Alton Brandon 20H-1	17-085-22478-00, 17-085-22479-00, & 17-085-22480-00	-	-	Pleasant Hill	Sabine	LA	71065	G2380
23	GEP Haynesville, LLC	McFarms ETAL 28H-001-Alt & 28H-002 Alt	17-081-21505-00 & 17-081-21506-00	-	-	East Point	Red River	LA	71019	G2380
24	GEP Haynesville, LLC	McFarms ETAL 28H-003-Alt & 28H-004 Alt	17-081-21507-00 & 17-081-21508-00	-	-	East Point	Red River	LA	71019	G2380
25	GEP Haynesville, LLC	Edgar Cason 3H- 2, 3, 4	17-081-21512-00, 17-081-21513-00, & 17-081-21514-00	-	-	East Point	Red River	LA	71019	G2380
26	GEP Haynesville, LLC	Murphy Bonded 3H-1, 2, 3	17-081-21509-00, 17-081-21510-00, & 17-081-21511-00	-	-	East Point	Red River	LA	71019	G2380
27	GEP Haynesville, LLC	Cecile Land 17H-2&3	17-081-21515-00 & 17-081-21516-00	-	-	East Point	Red River	LA	71019	G2380
28	GEP Haynesville, LLC	Cecile Land 17H-4&5	17-081-21517-00 & 17-081-21518-00	-	-	East Point	Red River	LA	71019	G2380

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report

For each affected facility, an owner or operator must include the information specified in paragraphs (b)(1)(i) through (iv) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

SITE INFORMATION			ALTERNATIVE ADDRESS INFORMATION (IF NO PHYSICAL ADDRESS AVAILABLE FOR SITE *)			
Facility Record No.* (Field value will automatically generate if a value is not entered.)	Company Name * (§60.5420a(b)(1)(i))	Facility Site Name * (§60.5420a(b)(1)(i))	US Well ID or US Well ID Associated with the Affected Facility, if applicable.* (§60.5420a(b)(1)(i))	Description of Site Location (§60.5420a(b)(1)(i))	Latitude of the Site (decimal degrees to 5 decimals using the North American Datum of 1983) (§60.5420a(b)(1)(i))	Longitude of the Site (decimal degrees to 5 decimals using the North American Datum of 1983) (§60.5420a(b)(1)(i))
1 GEP Haynesville, LLC	Bertolla 30-19HC 1-ALT & 30-31HC 1&2-ALT	17-081-21527-00	0.5 miles NW of the intersection of LA-514 & LA-515 near East Point, LA	32.17097	-93.43699	
2 GEP Haynesville, LLC	Cecile Land 9-4HC 1&2-ALT	17-081-21530-00 & 17-081-21531-00	3.0 miles SE of the intersection of LA-514 & LA-515 near East Point, LA	32.12908	-93.40316	
3 GEP Haynesville, LLC	GEP ETAL 9-4HC 1&2-ALT	17-081-21523-00 & 17-081-21524-00	3.2 miles SE of the intersection of LA-514 & LA-515 near East Point, LA	32.12892	-93.39654	
4 GEP Haynesville, LLC	James Marston 30-19HC 1-ALT & 30H-1	17-081-21532-00	0.8 miles NW of the intersection of LA-514 & LA-515 near East Point, LA	32.17670	-93.43498	
5 GEP Haynesville, LLC	James Marston 30-19HC 2&3-ALT & 30-31HC 1&2-ALT	17-081-21525-00 & 17-081-21526-00	0.4 miles NE of the intersection of LA-514 & LA-515 near East Point, LA	32.17103	-93.42865	
6 GEP Haynesville, LLC	Bolan ETAL 26-35HC 1,2 ALT	17-081-21543-00 & 17-081-21544-00	3.0 miles NE of the intersection of LA-1 N & LA-509 north of Grand Bayou, LA	32.17859	-93.46214	
7 GEP Haynesville, LLC	Bolan ETAL 27-34HC 001 ALT	17-081-21542-00	2.5 miles NW of the intersection of LA-1 & LA-509 north of Grand Bayou, LA	32.17230	-93.48295	
8 GEP Haynesville, LLC	Bollingham 18-7HC 001-ALT & 002-ALT	17-081-21548-00 & 17-081-21549-00	1.4 miles NW of the intersection of LA-155 & LA-507 near Martin, LA	32.10115	-93.23479	
9 GEP Haynesville, LLC	Bundrick 35-2 HC 001-ALT, 002-ALT & Bundrick 35H 001	17-081-21545-00 & 17-081-21546-00	1.5 miles NE of the intersection of LA-1 & LA-509 north of Grand Bayou, LA	32.15191	-93.46101	
10 GEP Haynesville, LLC	Olympia Min 2-11HC 001-ALT & Olympia Min 2-35HC 001	17-085-22461-00	3.2 miles SW of the intersection of LA-175 & LA-120 near Belmont, LA	31.70979	-93.56295	
11 GEP Haynesville, LLC	BRP LLC 23H-001ALT & Sustainable 23 001	17-031-26482-00	3.8 miles NE of the intersection of LA-175 & LA-509 near Mansfield, LA	32.09402	-93.66464	
12 GEP Haynesville, LLC	Marr ETAL 22-27HC-001 & 002	17-031-26523-00 & 17-031-26524-00	9.8 miles SE of the intersection of LA-175 & LA-509 near Mansfield, LA	31.93038	-93.59066	
13 GEP Haynesville, LLC	Madden 20-17HC 001-ALT, 17H 001 & 20H 001	17-081-21569-00	0.7 miles NE of the intersection of LA-71 & LA-514 near Hall Summit, LA	32.19289	-93.32208	
14 GEP Haynesville, LLC	Deanna Sistrunk 16H-02, 03, & 04 ALT and 9H-01, 02, & 03 ALT	17-085-22359-00, 17-085-22358-00, & 17-085-22357-00	2.1 miles SE of the intersection of LA-483 & LA-174 near Mitchell, LA	31.77175	-93.59995	
15 GEP Haynesville, LLC	Thomas Greer ETAL 16H-1, 17H-1 & Terry Greer 16H-1	17-085-22472-00 & 17-085-22473-00	1.8 miles SE of the intersection of LA-483 & LA-174 near Mitchell, LA	31.77170	-93.60796	
16 GEP Haynesville, LLC	Caney Creek Land 6H-2 and Caney Creek Land 6-1	17-081-21572-00	2.0 miles N of the intersection of Ashland Rd & Shreveport Rd near Coushatta, LA	32.05974	-93.33808	
17 GEP Haynesville, LLC	Moham ETAL 25-36HC 1,2,3 ALT	17-031-26558-00, 17-031-26572-00, & 17-031-26573-00	1.7 miles SW of the intersection of US-171 & LA-5 near Kickapoo, LA	32.17993	-93.86159	
18 GEP Haynesville, LLC	Two Mile 25-36HC 1ALT	17-031-26571-00	1.3 miles SW of the intersection of US-171 & LA-5 near Kickapoo, LA	32.17954	-93.85220	
19 GEP Haynesville, LLC	KHL Minerals 16-21HC-1	17-015-25114-00	1.0 miles SW of the intersection of Sligo Rd & Mayflower Rd near Sligo, LA	32.45709	-93.59777	
20 GEP Haynesville, LLC	Bozeman ETAL 20H 1,2 ALT	17-031-26581-00 & 17-031-26582-00	1.9 miles NW of the intersection of Stoddard St. & W. Main St. in Pleasant Hill, LA	31.84621	-93.52173	
21 GEP Haynesville, LLC	Hall ETAL 16-21HC 001	17-031-26635-00	1.6 miles NE of the intersection of US-171 & LA-3276 near Stonewall, LA	32.29604	-93.80311	
22 GEP Haynesville, LLC	Joan Brandon ETAL 20H 1,2,3 ALT & Alton Brandon 20H-1	17-085-22478-00, 17-085-22479-00, & 17-085-22480-00	0.7 miles NE of the intersection of Stoddard St. & W. Main St. in Pleasant Hill, LA	31.83003	-93.51291	
23 GEP Haynesville, LLC	McFarms ETAL 28H-001-Alt & 28H-002 Alt	17-081-21505-00 & 17-081-21506-00	1.7 miles SE of the intersection of LA-514 & LA-515 near East Point, LA	32.16193	-93.40188	
24 GEP Haynesville, LLC	McFarms ETAL 28H-003-Alt & 28H-004-Alt	17-081-21507-00 & 17-081-21508-00	2.2 miles SE of the intersection of LA-514 & LA-515 near East Point, LA	32.16172	-93.39372	
25 GEP Haynesville, LLC	Edgar Cason 3H- 2, 3,4	17-081-21512-00, 17-081-21513-00, & 17-081-21514-00	0.1 miles NW of the intersection of LA-1 N & LA-509 north of Grand Bayou, LA	32.13721	-93.48226	
26 GEP Haynesville, LLC	Murphy Bonded 3H-1, 2, 3	17-081-21509-00, 17-081-21510-00, & 17-081-21511-00	0.5 miles NW of the intersection of LA-1 N & LA-509 north of Grand Bayou, LA	32.13693	-93.48817	
27 GEP Haynesville, LLC	Cecile Land 17H-2&3	17-081-21515-00 & 17-081-21516-00	3.4 miles SE of the intersection of LA-514 & LA-515 near East Point, LA	32.11714	-93.41700	
28 GEP Haynesville, LLC	Cecile Land 17H-4&5	17-081-21517-00 & 17-081-21518-00	3.4 miles SE of the intersection of LA-514 & LA-515 near East Point, LA	32.11885	-93.41065	

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report
For each affected facility, an owner or operator must include the information specified in paragraphs (b)(1)(i) through (iv) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

SITE INFORMATION			REPORTING INFORMATION		PE Certification	ADDITIONAL INFORMATION	
Facility Record No.* (Field value will automatically generate if a value is not entered.)	Company Name * (§60.5420a(b)(1)(i))	Facility Site Name * (§60.5420a(b)(1)(i))	US Well ID or US Well ID Associated with the Affected Facility, if applicable.* (§60.5420a(b)(1)(ii))	Beginning Date of Reporting Period.* (§60.5420a(b)(1)(iii))	Ending Date of Reporting Period.* (§60.5420a(b)(1)(iii))	Please provide the file name that contains the certification signed by a qualified professional engineer for each closed vent system routing to a control device or process.* (§60.5420a(b)(12)) Please provide only one file per record.	Please enter any additional information.. Enter associated file name reference.
1	GEP Haynesville, LLC	Bertolla 30-19HC 1-ALT & 30-31HC 1&2-ALT	17-081-21527-00	10/21/2017	8/2/2018 NA	-	-
2	GEP Haynesville, LLC	Cecile Land 9-4HC 1&2-ALT	17-081-21530-00 & 17-081-21531-00	8/5/2017	8/2/2018 NA	-	-
3	GEP Haynesville, LLC	GEP ETAL 9-4HC 1&2-ALT	17-081-21523-00 & 17-081-21524-00	8/4/2017	8/2/2018 NA	-	-
4	GEP Haynesville, LLC	James Marston 30-19HC 1-ALT & 30H-1	17-081-21532-00	10/21/2017	8/2/2018 NA	-	-
5	GEP Haynesville, LLC	James Marston 30-19HC 2&3-ALT & 30-1HC 1&2-ALT	17-081-21525-00 & 17-081-21526-00	10/22/2017	8/2/2018 NA	-	-
6	GEP Haynesville, LLC	Bolan ETAL 26-35HC 1,2 ALT	17-081-21544-00	11/19/2017	8/2/2018 NA	-	-
7	GEP Haynesville, LLC	Bolan ETAL 27-34HC 001 ALT	17-081-21542-00	11/20/2017	8/2/2018 NA	-	-
8	GEP Haynesville, LLC	Bollingham 18-7HC 001-ALT & 002-ALT	17-081-21548-00 & 17-081-21549-00	12/14/2017	8/2/2018 NA	-	-
9	GEP Haynesville, LLC	Bundrick 35-2 HC 001-ALT, 002-ALT & Bundrick 35H 001	17-081-21545-00 & 17-081-21546-00	11/20/2017	8/2/2018 NA	-	-
10	GEP Haynesville, LLC	Olympia Min 2-11HC 001-ALT & Olympia Min 2-35HC 001	17-085-22461-00	12/8/2017	8/2/2018 NA	-	-
11	GEP Haynesville, LLC	BRP LLC 23H-001ALT & Sustainable 23 001	17-031-26482-00	12/29/2017	8/2/2018 NA	-	-
12	GEP Haynesville, LLC	Marr ETAL 22-27HC-001 & 002	17-031-26523-00 & 17-031-26524-00	1/28/2018	8/2/2018 NA	-	-
13	GEP Haynesville, LLC	Madden 20-17HC 001-ALT, 17H 001 & 20H 001	17-081-21569-00	2/13/2018	8/2/2018 NA	-	-
14	GEP Haynesville, LLC	Deanna Sistrunk 16H-02, 03, & 04 ALT and 9H-01, 02, 085-22358-00, & 17-085-22357-00 & 03 ALT	17-085-22359-00, 17-085-22358-00, & 17-085-22357-00	3/27/2018	8/2/2018 NA	-	-
15	GEP Haynesville, LLC	Thomas Greer ETAL 16H-1, 17H-1 & Terry Greer 16H-1	17-085-22472-00 & 17-085-22473-00	3/28/2018	8/2/2018 NA	-	-
16	GEP Haynesville, LLC	Caney Creek Land 6H-2 and Caney Creek Land 6-1	17-081-21572-00	5/20/2018	8/2/2018 NA	-	-
17	GEP Haynesville, LLC	Moham ETAL 25-36HC 1,2,3 ALT	17-031-26558-00, 17-031-26572-00, & 17-031-26573-00	5/18/2018	8/2/2018 NA	-	-
18	GEP Haynesville, LLC	Two Mile 25-36HC 1ALT	17-031-26571-00	5/17/2018	8/2/2018 NA	-	-
19	GEP Haynesville, LLC	KHL Minerals 16-21HC-1	17-015-25114-00	6/21/2018	8/2/2018 NA	-	-
20	GEP Haynesville, LLC	Bozeman ETAL 20H 1,2 ALT	17-031-26581-00 & 17-031-26582-00	7/8/2018	8/2/2018 NA	-	-
21	GEP Haynesville, LLC	Hall ETAL 16-21HC 001	17-031-26635-00	7/24/2018	8/2/2018 NA	-	-
22	GEP Haynesville, LLC	Joan Brandon ETAL 20H 1,2,3 ALT & Alton Brandon 20H-1	17-085-22478-00, 17-085-22479-00, & 17-085-22480-00	7/7/2018	8/2/2018 NA	-	-
23	GEP Haynesville, LLC	McFarms ETAL 28H-001-Alt & 28H-002 Alt	17-081-21505-00 & 17-081-21506-00	8/2/2017	8/2/2018 NA	-	-
24	GEP Haynesville, LLC	McFarms ETAL 28H-003-Alt & 28H 004-Alt	17-081-21507-00 & 17-081-21508-00	8/2/2017	8/2/2018 NA	-	-
25	GEP Haynesville, LLC	Edgar Cason 3H- 2, 3,4	17-081-21512-00, 17-081-21513-00, & 17-081-21514-00	8/2/2017	8/2/2018 NA	-	-
26	GEP Haynesville, LLC	Murphy Bonded 3H-1, 2, 3	17-081-21509-00, 17-081-21510-00, & 17-081-21511-00	8/2/2017	8/2/2018 NA	-	-
27	GEP Haynesville, LLC	Cecile Land 17H-2&3	17-081-21515-00 & 17-081-21516-00	8/2/2017	8/2/2018 NA	-	-
28	GEP Haynesville, LLC	Cecile Land 17H-4&5	17-081-21517-00 & 17-081-21518-00	8/2/2017	8/2/2018 NA	-	-

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced

After September 18, 2015 - 60.5420a(b) Annual Report

For each well affected facility, an owner or operator must include the information specified in paragraphs (b)(2)(i) through (iii) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. * (Select from dropdown list - may need to scroll up)	United States Well Number* (\$60.5420a(b)(1)(ii))	Records of deviations where well completion operations with hydraulic fracturing were not performed in compliance with the requirements specified in § 60.5375a. * (\$60.5420a(b)(2)(ii) and \$60.5420a(c)(1)(ii))	§60.5432a Low Pressure Wells	All Well Completions	Well Location * (\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(iii)(A)-(B))
			Please provide the file name that contains the Record of Determination and Supporting Inputs and Calculations * (\$60.5420a(b)(2)(ii) and \$60.5420a(c)(1)(vii)) Please provide only one file per record.	Well Completion ID * (\$60.5420a(b)(2)(i) and \$60.5420a(c)(1)(i))	
1 17-081-21527-00	N/A	N/A	Bertolla 30-19HC 1 ALT	32.17097, -93.43699	
2 17-081-21530-00	N/A	N/A	Cecile Land 9-4HC 1 ALT	32.12908, -93.40316	
2 17-081-21531-00	N/A	N/A	Cecile Land 9-4HC 2 ALT	32.12908, -93.40316	
3 17-081-21523-00	N/A	N/A	GEP ETAL 9-4HC 001-ALT	32.12892, -93.39654	
3 17-081-21524-00	N/A	N/A	GEP ETAL 9-4HC 002-ALT	32.12892, -93.39654	
4 17-081-21532-00	N/A	N/A	James Marston 30-19HC 1 ALT	32.17670, -93.43498	
5 17-081-21525-00	N/A	N/A	James Marston 30-19HC 2 ALT	32.17103, -93.42865	
5 17-081-21526-00	N/A	N/A	James Marston 30-19HC 3 ALT	32.17103, -93.42865	
6 17-081-21543-00	N/A	N/A	Bolan ETAL 26-35 HC 001 ALT	32.17859, -93.46214	
6 17-081-21544-00	N/A	N/A	Bolan ETAL 26-35 HC 002 ALT	32.17859, -93.46214	
7 17-081-21542-00	N/A	N/A	Bolan ETAL 27-34HC 001 ALT	32.17230, -93.48295	
8 17-081-21548-00	N/A	N/A	Bollingham 18-7HC 001 ALT	32.10115, -93.23479	
8 17-081-21549-00	N/A	N/A	Bollingham 18-7HC 002 ALT	32.10115, -93.23479	
9 17-081-21545-00	N/A	N/A	Bundrick 35-2 HC 001-ALT	32.15191, -93.46101	
9 17-081-21546-00	N/A	N/A	Bundrick 35-2 HC 002-ALT	32.15191, -93.46101	
10 17-085-22461-00	N/A	N/A	Olympia Min 2-11HC 001-ALT	31.70979, -93.56295	
11 17-031-26482-00	N/A	N/A	BRP LLC 23H-001ALT	32.09402, -93.66464	
12 17-031-26523-00	N/A	N/A	Marr ETAL 22-27HC-001	31.93038, -93.59066	
12 17-031-26524-00	N/A	N/A	Marr ETAL 22-27HC-002	31.93038, -93.59066	
13 17-081-21569-00	N/A	N/A	Madden 20-17HC 001-ALT	32.19289, -93.32208	
14 17-085-22359-00	N/A	N/A	Deanna Sistrunk 16H-02 ALT	31.77175, -93.59995	
14 17-085-22358-00	N/A	N/A	Deanna Sistrunk 16H-03 ALT	31.77175, -93.59995	
14 17-085-22357-00	N/A	N/A	Deanna Sistrunk 16H-04 ALT	31.77175, -93.59995	
15 17-085-22472-00	N/A	N/A	Thomas Greer ETAL 16H-1	31.77170, -93.60796	
15 17-085-22473-00	N/A	N/A	Thomas Greer ETAL 17H-1	31.77170, -93.60796	
16 17-081-21572-00	N/A	N/A	Caney Creek Land 6H-2	32.05974, -93.33808	
17 17-031-26558-00	N/A	N/A	Moham ETAL 25-36HC 1 ALT	32.17993, -93.86159	
17 17-031-26572-00	N/A	N/A	Moham ETAL 25-36HC 2 ALT	32.17993, -93.86159	
17 17-031-26573-00	N/A	N/A	Moham ETAL 25-36HC 3 ALT	32.17993, -93.86159	
18 17-031-26571-00	N/A	N/A	Two Mile 25-36HC 1ALT	32.17954, -93.85220	
19 17-015-25114-00	N/A	N/A	KHL Minerals 16-21HC-1	32.45709, -93.59777	
20 17-031-26581-00	N/A	N/A	Bozeman ETAL 20H 1 ALT	31.84621, -93.52173	
20 17-031-26582-00	N/A	N/A	Bozeman ETAL 20H 2 ALT	31.84621, -93.52173	
21 17-031-26635-00	N/A	N/A	Hall ETAL 16-21HC 001	32.29604, -93.80311	
22 17-085-22478-00	N/A	N/A	Joan Brandon ETAL 20H 1 ALT	31.83003, -93.51291	
22 17-085-22479-00	N/A	N/A	Joan Brandon ETAL 20H 2 ALT	31.83003, -93.51291	
22 17-085-22480-00	N/A	N/A	Joan Brandon ETAL 20H 3 ALT	31.83003, -93.51291	

The asterisk (*) next to each field indicates that the corresponding field is required.

All Well Completions

Facility Record No. * (Select Name and Department where record was created)	United States Well Number* (60.54204b1)(e)(i)	Date of Onset of Flowback Following Hydraulic Fracturing or Re-fracturing* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Time of Onset of Flowback or Hydraulic Fracturing or Re-fracturing* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Date of Each Attempt to Direct Flowback in a Separator* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Time of Each Attempt to Direct Flowback in a Separator* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Time of Each Attempt to Direct Flowback to a Sealant* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Time of Each Occurrence of Return to the Initial Flowback Stage* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Date of Each Occurrence of Return to the Initial Flowback Stage* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Date Well Shut In and Flowback Equipment Permanently Disconnected from the Startup of Production* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Date Well Shut In and Flowback Equipment Permanently Disconnected from the Startup of Production* (60.54204b1)(e)(i) and (60.54204c1)(e)(i)(A)(6))	Duration of Flowback in Hours * (Not Required for Wells Complying with §60.54204b1)(e)(i))	
1 17.08.2.1527.00	Bettina 30 19HC 1 A1	10/21/2017	4:30 AM	10/21/2017	9:30 AM	11/03 AM	N/A	11/03 AM	11/03 AM	11/03 AM	291	284
2 17.08.2.1530.00	Celite 9 4HC 2 A1	8/7/2017	9:30 AM	8/7/2017	9:30 AM	8/7/2017	9:30 AM	8/7/2017	9:30 AM	8/7/2017	5:00 AM	540.25
3 17.08.2.1531.00	GIFTA 1 9 4HC 0 A1	8/4/2017	10:30 AM	8/4/2017	10:30 AM	8/4/2017	11:00 AM	8/4/2017	11:00 AM	8/4/2017	5:00 AM	431
3 17.08.2.1534.00	GIFTA 1 9 4HC 02 0 A1	8/4/2017	10:30 AM	8/4/2017	10:30 AM	8/4/2017	11:00 AM	8/4/2017	11:00 AM	8/4/2017	5:00 AM	430
4 17.08.2.1532.00	Lamie Marlin 90 19HC 1 A1	10/21/2017	12:00 PM	10/21/2017	1:00 PM	N/A	N/A	11/03 AM	N/A	11/03 AM	6:00 AM	284.4
5 17.08.2.1535.00	Lamie Marlin 90 19HC 2 A1	10/21/2017	5:00 PM	10/21/2017	5:30 PM	N/A	N/A	11/03 AM	N/A	11/03 AM	6:00 AM	277
5 17.08.2.1536.00	Lamie Marlin 90 19HC 3 A1	10/21/2017	5:00 PM	10/21/2017	5:30 PM	N/A	N/A	11/03 AM	N/A	11/03 AM	6:00 AM	277
6 17.08.2.1543.00	Solan E1A1 26 35 HC 001 A1	11/19/2017	9:15 AM	11/19/2017	9:15 AM	11/19/2017	9:15 AM	11/19/2017	9:15 AM	11/19/2017	5:00 AM	219.75
6 17.08.2.1544.00	Solan E1A1 26 35 HC 002 A1	11/19/2017	9:41 AM	11/19/2017	9:41 AM	11/19/2017	10:00 AM	11/19/2017	10:00 AM	11/19/2017	6:00 AM	240.12
7 17.08.2.1542.00	Solan E1A1 27 34HC 001 A1	11/19/2017	12:30 PM	11/19/2017	1:00 PM	N/A	N/A	11/20/2017	1:00 PM	11/20/2017	5:00 AM	208.5
8 17.08.2.1548.00	Bellinger 18 2HC 001 A1	12/12/2017	8:17 AM	12/14/2017	8:17 AM	12/14/2017	8:30 AM	12/14/2017	8:30 AM	12/14/2017	5:00 AM	284.38
8 17.08.2.1549.00	Bellinger 18 2HC 002 A1	12/12/2017	8:00 AM	12/14/2017	8:00 AM	12/14/2017	8:15 AM	12/14/2017	8:15 AM	12/14/2017	5:00 AM	285
9 17.08.2.1545.00	Burke 35 2 HC 001 A1	11/20/2017	10:29 AM	11/20/2017	10:29 AM	11/20/2017	10:30 AM	11/20/2017	10:30 AM	11/20/2017	5:00 AM	258.52
9 17.08.2.1546.00	Burke 35 2 HC 002 A1	11/20/2017	9:15 AM	11/20/2017	9:15 AM	11/20/2017	9:15 AM	11/20/2017	9:15 AM	11/20/2017	5:00 AM	287.75
10 17.08.2.1541.00	Olympia Min 2 1HC 001 A1	12/07/2017	10:30 AM	12/07/2017	11:00 AM	12/08/2017	11:00 AM	12/08/2017	11:00 AM	12/08/2017	6:00 AM	259.83
11 17.08.2.1542.00	BPPLC 12/20/01 A1	12/27/2017	11:00 AM	12/27/2017	11:00 AM	12/27/2017	11:00 AM	12/27/2017	11:00 AM	12/27/2017	5:00 AM	234
12 17.08.2.1553.00	Marl E1A1 22 2HC 001 A1	1/2/2018	9:00 AM	1/2/2018	9:00 AM	1/2/2018	9:00 AM	1/2/2018	9:00 AM	1/2/2018	5:00 AM	188
12 17.08.2.1554.00	Marl E1A1 22 2HC 002 A1	1/2/2018	8:20 AM	1/2/2018	8:20 AM	1/2/2018	8:20 AM	1/2/2018	8:20 AM	1/2/2018	5:00 AM	188.67
13 17.08.2.1559.00	Marsden 20 17HC 001 A1	2/1/2018	10:00 AM	2/1/2018	11:00 AM	N/A	N/A	2/2/2018	11:00 AM	2/2/2018	6:00 AM	164
14 17.08.2.1519.00	Urana Mintrak 18/02 A1	3/2/2018	7:30 AM	3/2/2018	8:00 AM	3/2/2018	8:00 AM	3/2/2018	8:00 AM	3/2/2018	5:00 AM	187.5
14 17.08.2.2158.00	Urana Mintrak 18/01 A1	3/2/2018	7:00 AM	3/2/2018	7:00 AM	3/2/2018	7:00 AM	3/2/2018	7:00 AM	3/2/2018	5:00 AM	190
14 17.08.2.2157.00	Urana Mintrak 18/03 A1	3/2/2018	12:22 PM	3/2/2018	12:33 PM	3/2/2018	12:33 PM	3/2/2018	12:33 PM	3/2/2018	5:00 AM	184.63
15 17.08.2.2147.00	Thomas Green E1A1 17HC 1 A1	3/2/2018	3:20 PM	3/2/2018	4:00 PM	3/2/2018	4:00 PM	3/2/2018	4:00 PM	3/2/2018	5:00 AM	133.67
16 17.08.2.2143.00	Thomas Green E1A1 17HC 2 A1	3/2/2018	9:00 AM	3/2/2018	9:00 AM	3/2/2018	9:00 AM	3/2/2018	9:00 AM	3/2/2018	5:00 AM	133.67
16 17.08.2.2157.00	Camp Creek Landfill 2 A1	5/20/2018	12:00 PM	5/18/2018	1:00 PM	N/A	N/A	5/18/2018	1:00 PM	5/18/2018	5:00 AM	235.83
17 17.03.1.6558.00	Moham E1A1 25 3HC 0 A1	5/18/2018	3:15 PM	5/18/2018	4:00 PM	N/A	N/A	5/18/2018	4:00 PM	5/18/2018	5:00 AM	156.67
17 17.03.1.6572.00	Moham E1A1 25 3HC 2 A1	5/18/2018	12:25 PM	5/18/2018	1:00 PM	N/A	N/A	5/18/2018	1:00 PM	5/18/2018	5:00 AM	157
17 17.03.1.6573.00	Moham E1A1 25 3HC 3 A1	5/17/2018	11:00 AM	5/17/2018	12:00 PM	N/A	N/A	5/17/2018	12:00 PM	5/17/2018	5:00 AM	156.67
18 17.03.1.6574.00	Two Men 16 2HC 0 A1	6/2/2018	6:00 AM	6/2/2018	5:00 PM	N/A	N/A	6/2/2018	5:00 PM	6/2/2018	5:00 AM	21.12
19 17.03.1.5114.00	Edmunds E1A1 20HC 0 A1	6/1/2018	5:00 PM	6/1/2018	5:00 PM	N/A	N/A	6/1/2018	5:00 PM	6/1/2018	5:00 AM	156
20 17.03.1.6551.00	Edmunds E1A1 20HC 1 A1	6/1/2018	5:00 PM	6/1/2018	5:00 PM	N/A	N/A	6/1/2018	5:00 PM	6/1/2018	5:00 AM	156
21 17.03.1.6552.00	Edmunds E1A1 20HC 2 A1	6/1/2018	12:40 PM	6/1/2018	1:40 PM	N/A	N/A	6/1/2018	1:40 PM	6/1/2018	5:00 AM	25.8
22 17.03.1.2147.00	Joan Branson E1A1 20HC 1 A1	6/1/2018	8:34 AM	6/1/2018	10:00 AM	N/A	N/A	6/1/2018	10:00 AM	6/1/2018	5:00 AM	16.43
22 17.03.1.2147.00	Joan Branson E1A1 20HC 2 A1	6/1/2018	9:05 AM	6/1/2018	10:00 AM	N/A	N/A	6/1/2018	10:00 AM	6/1/2018	5:00 AM	16.43
22 17.03.1.2147.00	Joan Branson E1A1 20HC 3 A1	6/1/2018	9:15 AM	6/1/2018	10:00 AM	N/A	N/A	6/1/2018	10:00 AM	6/1/2018	5:00 AM	16.43

For each well affected facility, an owner or operator must include the information specified in paragraphs (b)(2)(i) through (iii) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

		All Well Completions		Well Affected Facilities Required to Comply with §60.5375(a) and §60.5375(a)	
Facility Record No.* (Select from dropdown list - may need to scroll up.)	United States Well Number* (§60.5420(a)(b)(1)(iii))	Well Completion ID * (§60.5420(a)(b)(2)(i) and §60.5420(a)(c)(1)(ii))	Disposition of Recovery * (§60.5420(a)(b)(2)(i) and §60.5420(a)(c)(1)(iii)(A)-(B))	Duration of Combustion in Hours * <td>Reason for Venting in lieu of Capture or Combustion * (§60.5420(a)(b)(2)(i) and §60.5420(a)(c)(1)(iii)(A)-(B))</td>	Reason for Venting in lieu of Capture or Combustion * (§60.5420(a)(b)(2)(i) and §60.5420(a)(c)(1)(iii)(A)-(B))
1	17-081-21527-00	Bertolla 30-19HC 1-ALT	Routed to sales line.	N/A	N/A
2	17-081-21530-00	Cecile Land 9-4HC 1 ALT	Routed to sales line.	N/A	N/A
3	17-081-21531-00	Cecile Land 9-4HC 2 ALT	Routed to sales line.	N/A	N/A
3	17-081-21523-00	GEP ET AL 9-4HC 001-ALT	Routed to sales line.	N/A	N/A
3	17-081-21524-00	GEP ET AL 9-4HC 002-ALT	Routed to sales line.	N/A	N/A
4	17-081-21532-00	James Marston 30-19HC 1 ALT	Routed to sales line.	N/A	N/A
5	17-081-21525-00	James Marston 30-19HC 2 ALT	Routed to sales line.	N/A	N/A
5	17-081-21526-00	James Marston 30-19HC 3 ALT	Routed to sales line.	N/A	N/A
6	17-081-21543-00	Bolan ET AL 26-35 HC 001 ALT	Routed to sales line.	N/A	N/A
6	17-081-21544-00	Bolan ET AL 26-35 HC 002 ALT	Routed to sales line.	N/A	N/A
7	17-081-21542-00	Bolan ET AL 27-34HC 001 ALT	Routed to sales line.	N/A	N/A
8	17-081-21548-00	Bollingham 18-7HC 001 ALT	Routed to sales line.	N/A	N/A
8	17-081-21549-00	Bollingham 18-7HC 002 ALT	Routed to sales line.	N/A	N/A
9	17-081-21545-00	Bundrick 35-2 HC 001-ALT	Routed to sales line.	N/A	N/A
9	17-081-21546-00	Bundrick 35-2 HC 002-ALT	Routed to sales line.	N/A	N/A
10	17-085-22461-00	Olympia Min 2-11HC 001-ALT	Routed to sales line.	N/A	N/A
11	17-031-26482-00	BRP LLC 23H-001ALT	Routed to sales line.	N/A	N/A
12	17-031-26523-00	Marr ET AL 22-27HC-001	Routed to sales line.	N/A	N/A
12	17-031-26524-00	Marr ET AL 22-27HC-002	Routed to sales line.	N/A	N/A
13	17-081-21569-00	Madden 20-17HC 001-ALT	Routed to sales line.	N/A	N/A
14	17-085-22359-00	Deanna Sistrunk 16H-02 ALT	Routed to sales line.	N/A	N/A
14	17-085-22358-00	Deanna Sistrunk 16H-03 ALT	Routed to sales line.	N/A	N/A
14	17-085-22357-00	Deanna Sistrunk 16H-04 ALT	Routed to sales line.	N/A	N/A
15	17-085-22472-00	Thomas Greer ET AL 16H-1	Routed to sales line.	N/A	N/A
15	17-085-22473-00	Thomas Greer ET AL 17H-1	Routed to sales line.	N/A	N/A
16	17-081-21572-00	Caney Creek Land 6H-2	Routed to sales line.	N/A	N/A
17	17-031-26558-00	Moham ET AL 25-36HC 1 ALT	Routed to sales line.	N/A	N/A
17	17-031-26572-00	Moham ET AL 25-36HC 2 ALT	Routed to sales line.	N/A	N/A
17	17-031-26573-00	Moham ET AL 25-36HC 3 ALT	Routed to sales line.	N/A	N/A
18	17-031-26571-00	Two Mile 25-36HC 1 ALT	Routed to sales line.	N/A	N/A
19	17-015-25114-00	KHL Minerals 16-21HC-1	Routed to sales line.	N/A	N/A
20	17-031-26581-00	Bozeman ET AL 20H 1 ALT	Routed to sales line.	N/A	N/A
20	17-031-26582-00	Bozeman ET AL 20H 2 ALT	Routed to sales line.	N/A	N/A
21	17-031-26635-00	Hall ET AL 16-21HC 001	Routed to sales line.	N/A	N/A
22	17-085-22478-00	Joan Brandon ET AL 20H 1 ALT	Routed to sales line.	N/A	N/A
22	17-085-22479-00	Joan Brandon ET AL 20H 2 ALT	Routed to sales line.	N/A	N/A
22	17-085-22480-00	Joan Brandon ET AL 20H 3 ALT	Routed to sales line.	N/A	N/A

The asterisk (*) next to each field indicates that the corresponding field is required.

All Well Completions		Exceptions Under 60.5375(a)(3) - Technically Infeasible to Route to the Gas Flow Line or Collection System, Re-inject into a Well, Use as an Onsite Fuel Source, or Use for Another Useful Purpose Served By a Purchased Fuel or Raw Material									
Facility Record No.* (Select from dropdown list - may need to scroll up)	United States Well Number* (§60.5420(a)(b)(1)(ii))	Well Location * (§60.5420(a)(b)(1)(ii) and §60.5420(a)(c)(1)(ii))	Well Completion ID * (§60.5420(a)(b)(1)(ii) and §60.5420(a)(c)(1)(ii))	Specific Exception Claimed * (§60.5420(a)(b)(1)(ii) and §60.5420(a)(c)(1)(ii))	Starting Date for the Period the Well Operated Under the Exception * (§60.5420(a)(b)(1)(ii) and §60.5420(a)(c)(1)(ii))	Ending Date for the Period the Well Meets the Claimed Exception * (§60.5420(a)(b)(1)(ii) and §60.5420(a)(c)(1)(ii))	Location of Nearest Gathering Line *	Technical Considerations Preventing Routing to this Line *	Capture, Rejection, and Reuse Technologies Considered *	Aspects of Gas or Equipment Preventing Use of Recovered Gas as a Fuel for Other Useful Purpose *	Additional Reasons for Technical Infeasibility *
1	17-081-21527-00	Bertolla 30-19HC-1 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	17-081-21530-00	Cecile Land 9-4HC-1 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	17-081-21533-00	GEP ETAL 9-4HC-001-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3	17-081-21524-00	GEP ETAL 9-4HC-002-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
4	17-081-21532-00	James Marston 30-19HC-1 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
5	17-081-21525-00	James Marston 30-19HC-2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
5	17-081-21526-00	James Marston 30-19HC-3 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6	17-081-21543-00	Bolian ETAL 26-35-HC-001-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6	17-081-21544-00	Bolian ETAL 26-35-HC-002-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
7	17-081-21542-00	Bolian ETAL 27-34HC-001-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8	17-081-21548-00	Bolingham 18-7HC-001 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8	17-081-21549-00	Bolingham 18-7HC-002 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
9	17-081-21545-00	Bundrick 35-2-HC-001-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
10	17-085-22461-00	Olympia Min 2-11HC-001-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
11	17-031-16482-00	BRP LLC 23H-001-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
12	17-031-26523-00	Marr ETAL 22-27HC-001	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
12	17-031-26544-00	Marr ETAL 22-27HC-002	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
13	17-081-21569-00	Madden 20-17HC-001-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
14	17-085-22359-00	Deanna Sistrunk 16H-02-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
14	17-085-22358-00	Deanna Sistrunk 16H-03-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
14	17-085-22357-00	Deanna Sistrunk 16H-04-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
15	17-085-22472-00	Thomas Green ETAL 16H-1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
15	17-085-22473-00	Thomas Green ETAL 17H-1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
16	17-081-21572-00	Caney Creek Land 6H-2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
17	17-031-26558-00	Moham ETAL 25-36HC-1 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
17	17-031-26572-00	Moham ETAL 25-36HC-2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
17	17-031-26573-00	Moham ETAL 25-36HC-3 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
18	17-031-26571-00	Two Mile 25-36HC-1 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
19	17-015-25114-00	KHL Minerals 16-21HC-1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
20	17-031-26581-00	Bozeman ETAL 20H 1 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
20	17-031-26582-00	Bozeman ETAL 20H 2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
21	17-031-26635-00	Hall ET AL 16-21HC-001	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
22	17-085-22478-00	Joan Brandon ETAL 20H 1 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
22	17-085-22479-00	Joan Brandon ETAL 20H 2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
22	17-085-22480-00	Joan Brandon ETAL 20H 3 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

The asterisk (*) next to each field indicates that the corresponding field is required.

		Well Affected Facilities Meeting the Criteria of 60.5375(a)(9)(ii)(A) - Not Hydraulically Fractured/Refractured with Liquids or Do Not Generate Condensate, Intermediate Hydrocarbon Liquids, or Produced Water (No Liquid Collection System or Separator Onsite)									
		All Well Completions					Well Completion				
Facility Record No. * [Select from dropdown list - may have to scroll up or down]	United States Well Number* [60.5420(a)(9)(ii)]	Well Location* [60.5420(b)(9)(ii)] and [60.5420(b)(10)]	Date of Onset of Hydraulic Fracturing or Refracturing* [60.5420(b)(2)] and [60.5420(c)(4)] and [60.5420(c)(10)]	Time of Onset of Flowback following Hydraulic Fracturing or Refracturing* [60.5420(b)(2)] and [60.5420(c)(4)] and [60.5420(c)(10)]	Date Well Shut-in and Flowback Equipment Permanently Disconnected or Decommissioned or Disconnected from the Startup of Production* [60.5420(b)(2)] and [60.5420(c)(4)] and [60.5420(c)(10)]	Duration of Flowback in Hours* [60.5420(b)(3)(v)(A)] and [60.5420(c)(3)(v)(A)]	Duration of Combustion in Hours* [60.5420(b)(2)(ii)] and [60.5420(c)(1)(ii)(A)] and [60.5420(c)(1)(ii)(C)]	Duration of Venting in Hours* [60.5420(b)(2)(ii)] and [60.5420(c)(1)(ii)(A)] and [60.5420(c)(1)(ii)(C)]	Reason for Venting in Hours* [60.5420(b)(2)(ii)] and [60.5420(c)(1)(ii)(A)] and [60.5420(c)(1)(ii)(C)]	If applicable: Does well still meet the conditions of capture or Combustion* [60.5420(b)(2)(ii)] and [60.5420(c)(1)(ii)(A)] and [60.5420(c)(1)(ii)(C)]	If applicable: Date Well Completion Operation Stopped* [60.5420(b)(2)(ii)] and [60.5420(c)(1)(ii)(A)] and [60.5420(c)(1)(ii)(C)]
1 17-081-21327-00	Bartolia 30-19HC-1 ALT	[Ceola and 9-4HC-1 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2 17-081-21350-00	Ceola and 9-4HC-2 ALT	[Ceola and 9-4HC-2 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
3 17-081-21351-00	GEP ETAL-4HC-001 ALT	[GEP ETAL-4HC-001 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
4 17-081-21352-00	GEP ETAL-4HC-002 ALT	[GEP ETAL-4HC-002 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
5 17-081-21353-00	James Marion 10-19HC-1 ALT	[James Marion 10-19HC-1 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6 17-081-21354-00	James Marion 10-19HC-2 ALT	[James Marion 10-19HC-2 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
7 17-081-21355-00	Boles ETAL-26-8HC-001 ALT	[Boles ETAL-26-8HC-001 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
8 17-081-21356-00	Boles ETAL-26-8HC-002 ALT	[Boles ETAL-26-8HC-002 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
9 17-081-21357-00	Boringgates 18-7HC-001 ALT	[Boringgates 18-7HC-001 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
10 17-081-21358-00	Burnside 3-5-2 HC-001 ALT	[Burnside 3-5-2 HC-001 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
11 17-081-21359-00	Dympa Min 2-1HC-001 ALT	[Dympa Min 2-1HC-001 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
12 17-081-21360-00	Marr ETAL-22-27HC-001	[Marr ETAL-22-27HC-001]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
13 17-081-21361-00	Maddison 20-1THC-001 ALT	[Maddison 20-1THC-001 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
14 17-081-21362-00	Dharma Saffron 14B-02 ALT	[Dharma Saffron 14B-02 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
15 17-081-21363-00	Dharma Saffron 14B-04 ALT	[Dharma Saffron 14B-04 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
16 17-081-21364-00	Thomas Green ETAL-16H-1	[Thomas Green ETAL-16H-1]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
17 17-081-21365-00	George Green ETAL-17H-1	[George Green ETAL-17H-1]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
18 17-081-21366-00	George Green ETAL-17H-2	[George Green ETAL-17H-2]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
19 17-081-21367-00	McNamee ETAL-25-5HC-3 ALT	[McNamee ETAL-25-5HC-3 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
20 17-081-21368-00	Kell Materials 16-2HC-1	[Kell Materials 16-2HC-1]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
21 17-081-21369-00	Bazeman ETAL-20H-1 ALT	[Bazeman ETAL-20H-1 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
22 17-081-21370-00	Hall ETAL-6-1HC-001	[Hall ETAL-6-1HC-001]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
23 17-081-21371-00	Joan Brandon ETAL-20H-1 ALT	[Joan Brandon ETAL-20H-1 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
24 17-081-21372-00	Joan Brandon ETAL-20H-2 ALT	[Joan Brandon ETAL-20H-2 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
25 17-081-21373-00	Joan Brandon ETAL-20H-3 ALT	[Joan Brandon ETAL-20H-3 ALT]	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. [Select from dropdown list - n list - inferred to scroll up]	All Well Completions	Well Affected Facilities Meeting the Criteria of §60.5375(a)(1)(ii)(A) - Not Hydraulically Fractured/Reflected with Liquids or Produced Water (No Liquid Collection System or Separator Onsite)		Well Affected Facilities Required to Comply with Both §60.5375(a)(1) and (3) Using a Digital Photo or Line of Records Required by §60.542(a)(1)(ii) through (iv)	Well Affected Facilities Meeting the Criteria of §60.5375(a)(- <100 scf of Gas per Stock Tank Barrel of Oil Produced
		Well Completion ID * (§60.542(a)(b)(2)(i) and §60.542(a)(1)(ii))	Date Separator Installed * (§60.542(a)(b)(2)(i) and §60.542(a)(c)(1)(ii)(C)(2))		
11270812-15272.00	Bentota 30-15HC-1-4L1	N/A	N/A	Are there liquid collection at the well site? Based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete *	Does the well meet the requirements of §60.5375(a)? Based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete *
2170812-1550-00	Cecile Land 9-4HC-1 ALT	N/A	N/A	Please provide the file name that contains the Digital Photograph with Date Taken and Latitude and Longitude Imbedded (or with Visible GPS), Showing Required Equipment (§60.542(a)(b)(2)(i) and §60.542(a)(c)(1)(ii)) Please provide only one file per record.	Please provide the file name that contains the Record of Analysis Performed to Claim Well Meets §60.5375(a)(1) including GRS for Substituted Lessee and Data from Wells in the Same Basin and Field • (§60.542(a)(b)(2)(i) and §60.542(a)(c)(1)(ii)) Please provide only one file per record.
2170812-1551-00	Cecile Land 9-4HC-2 ALT	N/A	N/A		
3170812-1553-00	GEP ITAL 9-4HC-001 ALT	N/A	N/A		
4170812-1554-00	GEP ITAL 9-4HC-002 ALT	N/A	N/A		
5170812-1552-00	James Marston 30-19HC-1 ALT	N/A	N/A		
5170812-1575-00	James Marston 30-19HC-2 ALT	N/A	N/A		
5170812-1576-00	James Marston 30-19HC-3 ALT	N/A	N/A		
6170812-1541-00	Boian ITAL 26-35HC-001 ALT	N/A	N/A		
6170812-1544-00	Boian ITAL 26-35HC-002 ALT	N/A	N/A		
7170812-1542-00	Boian ITAL 27-35HC-001 ALT	N/A	N/A		
8170812-1548-00	Boilintham 18-27HC-001 ALT	N/A	N/A		
9170812-1549-00	Boilintham 18-27HC-002 ALT	N/A	N/A		
9170812-1545-00	Bundrick 35-2 HC-001-ALT	N/A	N/A		
9170812-1546-00	Bundrick 35-2 HC-002-ALT	N/A	N/A		
10170812-1461-00	Olymnia Min 21-1HC-001 ALT	N/A	N/A		
11170312-1542-00	S&P L/C 23HC-001 ALT	N/A	N/A		
12170312-1553-00	Warr ITAL 22-27HC-001	N/A	N/A		
13170312-1554-00	Warr ITAL 22-27HC-002	N/A	N/A		
14170812-2359-00	Maddsen 20-17HC-001 ALT	N/A	N/A		
14170812-2358-00	Deanna Sistrunk 16H-02 ALT	N/A	N/A		
15170812-2357-00	Deanna Sistrunk 16H-03 ALT	N/A	N/A		
15170812-2422-00	Thomas Green ITAL 16H-3	N/A	N/A		
15170812-2431-00	Thomas Green ITAL 17H-1	N/A	N/A		
16170812-2522-00	Carter Creek 16H-2	N/A	N/A		
17170312-2558-00	Woham ET AL 15-38HC-1 ALT	N/A	N/A		
17170312-2557-00	Woham ET AL 25-38HC-2 ALT	N/A	N/A		
17170312-2553-00	Woham ET AL 25-38HC-3 ALT	N/A	N/A		
18170312-2551-00	Two Mills 25-38HC 1 ALT	N/A	N/A		
19170312-2514-00	Kite Minerals 16-21HC-1	N/A	N/A		
20170312-2551-00	Rosenmark ETAL 20H-1 ALT	N/A	N/A		
20170312-2552-00	Rosenmark ETAL 20H-2 ALT	N/A	N/A		
21170312-2655-00	W.E ITAL 16-21HC-001	N/A	N/A		
21170812-2478-00	John Brandon ETAL 20H-2 ALT	N/A	N/A		
22170812-2479-00	John Brandon ETAL 20H-3 ALT	N/A	N/A		
22170812-2480-00	John Brandon ETAL 20H-3 ALT	N/A	N/A		

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. * (Select from dropdown list - may need to scroll up)		For centrifugal compressors using a wet sea system, was the compressor constructed, modified or reconstructed during the reporting period? * (\$60.5420(a)(3)(ii))	Deviations where the centrifugal compressor was not operated in compliance with requirements * (\$60.5420(b)(3)(ii) and \$60.5420(c)(2))	Record of Each Closed Vent System Inspection * (\$60.5420(b)(3)(ii) and \$60.5420(c)(6))	Record of Each Cover Inspection * (\$60.5420(b)(3)(iii) and \$60.5420(c)(7))	Centrifugal Compressors Required to Comply with 40 CFR 204(e)(2) Cover and Closed Vent System Requirements
N/A						If you are subject to the bypass requirements of 40 CFR 60.5420(a)(4) and you monitor the bypass with a flow indicator, a record of each time the alarm is sounded * (\$60.5420(b)(3)(ii) and \$60.5420(c)(3))

Centrifugal Compressors Required to Comply with 40 CFR 204(e)(2) Cover and Closed Vent System Requirements

If you are subject to the bypass requirements of 40 CFR 60.5420(a)(4) and you use a secured valve, a record of each time the key is checked out. * (\$60.5420(b)(3)(ii) and \$60.5420(c)(8))	If you are subject to the bypass requirements of 40 CFR 60.5420(a)(4) and you use a secured valve, a record of each monthly inspection * (\$60.5420(b)(3)(ii) and \$60.5420(c)(8))	Record of No Detectable Emissions Monitoring Conducted According to 40 CFR 60.5420(b)* (\$60.5420(b)(3)(ii) and \$60.5420(c)(9))
---	---	---

40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 16, 2015 - 40 CFR 60.42(a)(5) Annual Report
For each certificated compressor affected facility, an owner or operator must include the information specified in paragraphs (b)(3)(ii) through (v) of this section in all annual reports.

The asterisk (*) next to each field indicates that the corresponding field is required.

Centralized Compressors with Carbon Absorption		Centrifugal Compressors Subject to Control Device Requirements of 40 CFR 60.42(a)(6)		Centrifugal Compressors Using a Wet Seal System Constructed, Modified, or Reconstructed During Reporting Period with Control Device Fired Under 40 CFR 60.42(a)(6)	
Facility Record No. * [Select from dropdown list - may need to scroll up] [MO-54-2020-000000000000000000]	Records of the Method for Carbon Absorption [Information for analysis - (MO-54-2020-00000000000000000000)] [MO-54-2020-00000000000000000000]	Records of Each Carbon Replacement* [Information for analysis - (MO-54-2020-00000000000000000000)] [MO-54-2020-00000000000000000000]	Please provide the file name that contains the Configuration Parameter Monitoring System Data* [MO-54-2020-00000000000000000000] and [MO-54-2020-00000000000000000000] Please provide the file name that contains: [MO-54-2020-00000000000000000000]	Please provide the file name that contains the Configuration Parameter Monitoring System Data* [MO-54-2020-00000000000000000000] and [MO-54-2020-00000000000000000000] Please provide the file name that contains: [MO-54-2020-00000000000000000000]	Please provide the file name that contains the Configuration Parameter Monitoring System Data* [MO-54-2020-00000000000000000000] and [MO-54-2020-00000000000000000000] Please provide the file name that contains: [MO-54-2020-00000000000000000000]
N/A					

40 CFR Part 61, Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 14, 2013, 40 CFR (Final Action Report for new construction component affected facility, an owner or operator must include the information specified in paragraph (b)(5) of this section in all annual reports.)

The sections (b)(5) refer to each field indicated that the corresponding field is exempted.

Confidential Information Under E.O. 14176 and Subject Commodity, Brand and Product Reporting Period with Central Data Portal Under E.O. 14176					

Confidential Information Under E.O. 14176 and Subject Commodity, Brand and Product Reporting Period with Central Data Portal Under E.O. 14176					

For each reciprocating compressor affected facility, an owner or operator must include the information specified in paragraphs (b)(4)(i) and (ii) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No.* (Select from dropdown list - may need to scroll up)	Compressor ID * (§60.5420(a)(b)(1)(iii)) Are emissions from the rod packing unit being routed to a process through a closed vent system under negative pressure, what are the cumulative number of hours or months of operation since initial startup or the previous rod packing replacement (whichever is later)? * (§60.5420(a)(b)(4)(ii)) N/A	If emissions are not routed to a process through a closed vent system under negative pressure, what are the cumulative number of hours or months of operation since initial startup or the previous rod packing replacement (whichever is later)? * (§60.5420(a)(b)(4)(ii))	Units of Time Measurement (§60.5420(b)(4)(i))	Deviations where the reciprocating compressor was not operated in compliance with requirements * (§60.5420(b)(4)(ii) and §60.5420(a)(c)(3)(iii))
--	---	--	--	---

The asterisk (*) next to each field indicates that the corresponding field is required.

Pneumatic Controller Identification *		Month of Installation, Reconstruction, or Modification*		Year of Installation, Reconstruction, or Modification*		Documentation that Use of a Pneumatic Controller with a Natural Gas Bleed Rate Greater than 6 Standard Cubic Feet per Hour is required *		Reasons Why * (§60.5420(a)(b)(5)(ii))		Records of deviations where the pneumatic controller was not operated in compliance with requirements* (§60.5420(a)(b)(5)(iii))	
Facility Record No. * (Select from dropdown list may need to scroll up)	Pneumatic Controller Identification * (§60.5420(a)(b)(1)(i)), §60.5420(a)(b)(5)(i), and §60.5390(a)(b)(2) or §60.5390(a)(c)(2))	Was the pneumatic controller constructed, modified or reconstructed during the reporting period?* (§60.5420(a)(b)(5)(ii))	(§60.5420(a)(b)(5)(i)) and §60.5390(a)(b)(2) or §60.5390(a)(c)(2))	(§60.5420(a)(b)(5)(i)) and §60.5390(a)(b)(2) or §60.5390(a)(c)(2))							

N/A

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. • <i>(Select from dropdown list. may need to scroll up)</i>	Storage Vessel ID • <i>(§60.5420(a)(1)(i) and §60.5420(a)(5)(ii))</i>	Was the storage vessel constructed, modified or reconstructed during the reporting period? *	Latitude of Storage Vessel (Decimal Degrees to 5 Decimals Using the North American Datum of 1983)* <i>(§60.5420(a)(6)(i))</i>	Longitude of Storage Vessel (Decimal Degrees to 5 Decimals Using the North American Datum of 1983)* <i>(§60.5420(a)(6)(i))</i>	If new affected facility or if returned to service during the reporting period, provide documentation of the VOC emission rate determination according to 60.5420(a)(6)(i) * <i>(§60.5420(a)(6)(i))</i>	Records of deviations where the storage vessel was not operated in compliance with requirements.* <i>(§60.5420(a)(6)(i)(iii) and §60.5420(a)(c)(5)(iii))</i>	Have you met the requirements specified in §60.5410(a)(1) and (3)?* <i>(§60.5420(a)(6)(iv))</i>	Removed from service during the reporting period? * <i>(§60.5420(a)(6)(o))</i>	If removed from service, the date removed from service. * <i>(§60.5420(a)(6)(v))</i>	Returned to service during the reporting period? * <i>(§60.5420(a)(6)(w))</i>	If returned to service, the date returned to service. * <i>(§60.5420(a)(6)(x))</i>
N/A											

The asterisk (*) next to each field indicates that the corresponding field is required.

Storage Vessels Constructed, Modified, Reconstructed or Returned to Service During Reporting Period that Comply with § 60.5395(a)(2) with a Control Device Tested Under § 60.5413(a)(d)						
Facility Record No. *	Storage Vessel ID * (§60.5420(a)(b)(1)(ii) and §60.5420(a)(b)(6)(i))	Make of Purchased Device * (§60.5420(a)(b)(6)(i)(vii) and §60.5420(a)(c)(6)(i))	Model of Purchased Device * (§60.5420(a)(b)(6)(vii) and §60.5420(a)(c)(5)(vii)(A))	Serial Number of Purchased Device * (§60.5420(a)(b)(6)(vii) and §60.5420(a)(c)(5)(vii)(A))	Date of Purchase * (§60.5420(a)(b)(6)(vii) and §60.5420(a)(c)(5)(vii)(B))	Copy of Purchase Order * (§60.5420(a)(b)(6)(vii) and §60.5420(a)(c)(5)(vii)(C))
N/A	N/A					

For each storage vessel affected facility, an owner or operator must include the information specified in paragraphs (b)(6)(i) through (vii) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

Storage Vessels Constructed, Modified, Reconstructed or Returned to Service During Reporting Period that Comply with 60.5395(a)(2) with a Control Device Tested Under § 60.5413(a)(d)			
Facility Record No. * (Select from dropdown list - may need to scroll up)	<p>Storage Vessel ID *</p> <p>(§60.5420(a)(b)(1)(i)) and §60.5420(a)(b)(6)(i))</p> <p>Inlet Gas Flow Rate *</p> <p>(§60.5420(a)(b)(6)(i)(vii) and §60.5420(a)(c)(5)(v)(E))</p>	<p>Please provide the file name that contains the Records of Pilot Flame Present at All Times of Operation *</p> <p>(§60.5420(a)(b)(6)(vii) and §60.5420(a)(c)(5)(v)(F)(1))</p> <p>Please provide only one file per record.</p>	<p>Please provide the file name that contains the Records of No Visible Emissions Periods Greater Than 1 Minute During Any 15-Minute Period *</p> <p>(§60.5420(a)(b)(6)(vii) and §60.5420(a)(c)(5)(v)(F)(2))</p> <p>Please provide only one file per record.</p>
N/A			<p>Please provide the file name that contains the Records of Visible Emissions Test Following Return to Operation From Maintenance and Repair Log *</p> <p>(§60.5420(a)(b)(6)(vii) and §60.5420(a)(c)(5)(v)(F)(3))</p> <p>Please provide only one file per record.</p>

The asterisk (*) next to each field indicates that the corresponding field is required.

^a 40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.542(a)(b) Annual Report
For the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each compressor station within the company-defined area, an owner or operator must include the records of each monitoring survey including the information specified in paragraphs (b)(7)(i) through (xii) of this section in all annual reports.

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. *	Identification of Each Affected Facility *	Type of Component Not Repaired as Required in § 60.5397(a)(4) *	Number of Each Component Type Not Repaired as Required in § 60.5397(a)(4) *	Type of Difficult-to-Monitor Components Monitored *	Number of Each Difficult-to-Monitor Component Type Monitored *	Type of Unsafe-to-Monitor Components Monitored *	Number of Each Unsafe-to-Monitor Component Type Monitored *	Date of Successful Repair of Fugitive Emissions Component *	Type of Component Placed on Delay of Repair *	Number of Each Component Type Placed on Delay of Repair *	Explanation for Delay of Repair *	Type of Instrument Used to Recovery Repaired Components Not Repaired During Original Survey *
	(Select from dropdown list, may need to scroll up)	(§60.542(a)(b)(7)(viii))	(§60.542(a)(b)(7)(vi))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))	(§60.542(a)(b)(7)(e))
1 Bertolla 30-19-HC-1-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
1 Bertolla 30-19-HC-1-ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 9-4HC-1&2- 2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 9-4HC-1&2- 2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
GEP ETAL 9-4HC-1&2- 2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	11/14/2017	N/A	N/A	N/A	N/A
James Marston 30-19-HC- 4-001 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
James Marston 30-19-HC- 4-002 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
James Marston 30-19-HC- 5-1&2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
James Marston 30-19-HC- 5-1&2 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Bolan ETAL 26-35-HC-1,2- 6 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Bolan ETAL 26-35-HC-1,2- 6 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	6/12/2017	N/A	N/A	N/A	N/A
Bolan ETAL 26-35-HC-1,2- 7 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	5/13/2017	N/A	N/A	N/A	N/A
Bolan ETAL 27-34-HC-001- 7 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Bolton 18-THC-001- 8 ALT & 301 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	2/6/2018	N/A	N/A	N/A	N/A
Bundrick 35-2-HC-001- 9 ALT 001 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Bundrick 35-2-HC-001- 9 ALT 002 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Olympia Min 2-11HC- 12001 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
11-BR01 LLC 23H001 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Mary ETAL 22-27HC-001- 121 & 102	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Madsen 20-17HC-001- 13 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Deanna Sitrunk 15H- 1402, 018 & 04 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Thomas Green ETAL 15H- 171, 17H-1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Carney Creek Land 6H-2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Moham ETAL 25-36-HC- 1,2 ALT & Moham ETAL 175, 36H-3	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Twin Mile 25-36HC-1,2- 19 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
KHL Minerals 16-21HC-3-N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Bozeman ETAL 20H-1,2- 20 ALT	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Hall ETAL 16-21HC-001	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Joan Brandon ETAL 20H- 21, 22, 3 AL	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
McFarlane ETAL 28H+001- 23 Alt & 28H-001 Alt	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
McFarlane ETAL 28H+001- 23 Alt & 28H-002 Alt	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
McFarlane ETAL 28H+001- 24 Alt & 28H-003 Alt	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
McFarlane ETAL 28H+001- 24 Alt & 28H-004 Alt	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
McFarlane ETAL 28H+003- 24 Alt & 28H-004 Alt	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Edgar Cason Min 2-1,4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Edgar Cason Min 2-1,4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Edgar Cason Min 2-1,4	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Murphy Bounded 3H-1,2- 24	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Murphy Bounded 3H-1,2- 26	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Murphy Bounded 3H-1,2- 26	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 17H-2,3- 27	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 17H-2,3- 27	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 17H-4&5- 28	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 17H-4&5- 28	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 17H-4&5- 28	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Cecile Land 17H-4&5- 28	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

* 40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420(a)(b) Annual Report
For the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each compressor station within the company-defined area, an owner or operator must include the records of each monitoring survey including the information specified in paragraphs (b)(7)(i) through (xii) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No.* (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (§60.5420(a)(b)(1))	OGI Training and Experience of Surveyor * (§60.5420(a)(b)(7)(iii))	Compressor Station Affected Facility Only	
			Was a monitoring survey waived under § 60.5997(a)(5) * (§60.5420(a)(b)(7))	If a monitoring survey was waived, the calendar months that make up the quarterly monitoring period for which the monitoring survey was waived. * (§60.5420(a)(b)(7))
1 Bertolla 30-19HC 1 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
1 Bertolla 30-19HC 1 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
2 Cecile Land 9-4HC 1&2 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
2 Cecile Land 9-4HC 1&2 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
3 GEP ETAL 9-4HC 1&2 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
3 GEP ETAL 9-4HC 1&2 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
James Marston 30-19HC 001 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
James Marston 30-19HC 001 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
James Marston 30-19HC 2&3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
James Marston 30-19HC 2&3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
6 Bolan ETAL 26-15HC 1,2 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
6 Bolan ETAL 26-15HC 1,2 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
6 Bolan ETAL 26-15HC 1,2 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
7 Bolan ETAL 27-34HC 001 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
7 Bolan ETAL 27-34HC 001 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
Bolingham 18-7HC 001 ALT & 002 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
Bundrick 35-2 HC 001 ALT, 002 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
Bundrick 35-2 HC 001 ALT, 002 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
10 Olympia Min 2-11HC 001 ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
11 BRP LLC 23H-001ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
Marr ETAL 22-27HC 001 & 12002	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
13 Maddsen 20-17HC 001 ALT, Deanna Sistrunk 16H 02, 03 & 14/4K ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
15 Thomas Greer ETAL 16H 1, 15-17 H 1	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
16 Caney Creek Land 6H 2	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
Moham ETAL 25-36HC 1,2 ALT & Moham ETAL 25-36H 3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
18 Two Mile 25-36HC 1ALT	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
19 KHI Minerals 16-21HC-1	HES Specialist with 7 years experience as an OGI surveyor; Certified API 510 Pressure Vessel Inspector (#47212), API 570 Piping Inspector (#49244), API 653 Inspector (#6015), Steel Tank Institute Inspector STI-SPO01 (#AC44206), & ASNT Level II Certified UT and PT.	N/A	N/A	
20 Bozeman ETAL 20H 1,2 ALT	HES Specialist with 6 years experience as an OGI surveyor; NORM/TENORM Surveyor, ASNT Level II Certified UT and Visual	N/A	N/A	
21 Hall ETAL 16-21HC 001	HES Specialist with 6 years experience as an OGI surveyor; NORM/TENORM Surveyor, ASNT Level II Certified UT and Visual	N/A	N/A	
Joan Brandon ETAL 20H 1,2,3 22 ALT	HES Specialist with 7 years experience as an OGI surveyor; Certified API 510 Pressure Vessel Inspector (#47212), API 570 Piping Inspector (#49244), API 653 Inspector (#6015), Steel Tank Institute Inspector STI-SPO01 (#AC44206), & ASNT Level II Certified UT and PT.	N/A	N/A	
McFarlams ETAL 28H-001 AR & 28H 002 AR	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
McFarlams ETAL 28H-001 AR & 28H 002 AR	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
McFarlams ETAL 28H-001 AR & 28H 002 AR	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
McFarlams ETAL 28H-003 AR & 28H 004 AR	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
McFarlams ETAL 28H-003 AR & 28H 004 AR	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
25 Edgar Cason 3H - 2, 3,4	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
25 Edgar Cason 3H - 2, 3,4	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
25 Edgar Cason 3H - 2, 3,4	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
26 Murphy Bonded 1H 1, 2, 3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
26 Murphy Bonded 1H 1, 2, 3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
26 Murphy Bonded 1H 1, 2, 3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
27 Cecile Land 17H 2&3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
27 Cecile Land 17H 2&3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
27 Cecile Land 17H 2&3	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
28 Cecile Land 17H 4&5	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
28 Cecile Land 17H 4&5	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	
28 Cecile Land 17H 4&5	HES Specialist with 5 years experience as an OGI surveyor; NORM/TENORM Surveyor	N/A	N/A	

The asterisk (*) next to each field indicates that the corresponding field is required.

Pneumatic Pump Previously Reported that have a Change in Reported Condition During the Reporting Period			
Facility Record No * [Select from dropdown list - may need to scroll up]	Identification of Each Pump * [§60.542(a)(b)(1)]	If your route emissions to a control device and the control device is designed to achieve <95% emissions reduction, specify the percent emissions reduction. *	Identification of Each Pump * [§60.542(a)(b)(8)(ii)]
		[§60.542(a)(b)(8)(ii)]	Date Previously Reported * [§60.542(a)(b)(8)(ii)]
N/A		[§60.542(a)(b)(8)(ii)]	Date Previously Reported * [§60.542(a)(b)(8)(ii)]
			Which condition does the pneumatic pump meet? *
			[§60.542(a)(b)(8)(ii)]
			Records of deviations where the pneumatic pump was not operated in compliance with requirements* [§60.542(a)(b)(8)(ii) and §60.542(a)(c)(16)(ii)]